CERTIFICATE

CERTIFIED PLAYGROUND SAFETY INSPECTOR
Certificate no. 076



Nordic Playground Institute Denmark hereby certifies:

Sandra Cristina Veríssimo Simões, born on October 6th, 1972, has completed the training:

CERTIFIED PLAYGROUND SAFETY INSPECTOR

- having acquired the knowledge and competencies in the understanding of the valid standards mentioned below, including inspection of equipment, reporting, and use of relevant testing equipment.

| ovant tooting oquipmont. | |
|--------------------------|--|
| EN 1176-1 | Playground equipment and surfacing - General safety measures and tests |
| EN 1176-2 | Swings - Additional safety measures and testing methods |
| EN 1176-3 | Slides - Additional safety measures and testing methods |
| EN 1176-4 | Cableways - Additional safety measures and testing methods |
| EN 1176-5 | Carousels - Additional safety measures and testing methods |
| EN 1176-6 | Rocking equipment - Additional safety measures and testing |
| EN 1176-7 | Guidance on maintenance, inspection, and operation |
| EN 1176-10 | Fully enclosed playground equipment - Additional measures |
| EN 1176-11 | 3-dimensional climbing structures - Additional safety measures |
| EN 1177 | Impact attenuating playground surfacing |
| EN 14974 | Skateparks – Safety measures |
| EN 15312 | Free access multi-sports equipment |
| EN 16630 | Permanently installed outdoor fitness equipment |
| EN 16899 | Sports and recreational equipment – Parkour |



Initial certification: 2025

This certificate is valid for the following inspections: Post installation, operational and annual, until: May 8th, 2028, unless revoked earlier.

Place: Næstved Date: August 21st, 2025

Einar Jon Skulason Hansen Group Chief Executive Officer



NORDIC PLAYGROUND INSTITUTE

Nordic Playground Institute

DENMARK

www.nlpi.dk

Maglemoelle 21 DK4700 Naestved, Denmark Telephone +45 70 70 78 17 Mail: info@nlpi.dk www.nlpi.dk